
| CITY OF BALTIMORE WET W SMOKE AND DYED W | Page 1 of 4 | |
|---|-----------------------|--|
| Sewershed: JONES FALLS | Company: REI/DRAYCO | Date: 06/13/08 |
| Test to be Performed: SMOKE | Ground Condition: DRY | Supervisor: ER |
| Manhole ID: S37MM_012MH | Test ID: 0994-344 | Notifications Made:_X (Residents, Fire, 311) |

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



| CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM | | | | | | | Page 2 of 4 | | |
|--|-------------------------------------|----------------|--------------------|---------------------|----------|--|------------------|----------|--------------|
| Sewershed: JONES FALLS | | | Compan | Company: REI/DRAYCO | | | Date: 06/13/2008 | | |
| Test to be Performed: | | | Ground Condition: | | | Supervisor:E.R | | | |
| Smoke:X Dyed Water: | | | Dry: _X Damp: Wet: | | | | | | |
| Manhole ID: S37MM_012MH | | | Test ID: 0994-344 | | | Notifications Made:X (Residents, Fire, 311) | | | |
| | Sketch: (Showons, Street Nam | | | | | | | _ | |
| Defect | | | | Source | · | | Drainage | | , |
| No. | | Address | | Type | Location | Sector | Area | Severity | Photo Number |
| 1 | 523 E. 20TH S | Γ. | | 03 | 01 | 02 | 0 | 02 | 344_OB01-01 |
| 2 | 1917 GREENM | OUNT AVE. | | 03 | 08 | 02 | 0 | 02 | 344_OB02-01 |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | OBSERV | ATION | CODES | | | |
| | Source Type | Location | Sector | Severity | | Source Type | Location | | |
| 01 | Main Sewer | Paved Concrete | Public | No Smoke | 10 | MH Frame S | Non-Paved | | |
| 02 | Service Line | Paved Asphalt | Private | Trace | 11 | Storm Drain | Field/Woods | | |
| 03 | Cleanout | Paved Other | | Moderate | 12 | Catch Basin/ | Alley | | |
| 04 | Downspout | Driveway | | Major | 13 | Storm Manh | Golf Course | | |
| 05 | Area Drain | Sidewalk | | | 14 | Storm Ditch | Other | | |
| 06 | Driveway Drain | Curb | | | 15 | Excavation | | | |
| 07 | Stairwell Drain | Yard- Front | | | 16 | Other | | | |
| | Foundation Drain | Yard-Back | | | | | | | |
| 09 | Building Interior | Yard- Side | | | | | | | |

PAGE 3 OF 4

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY JONES FALLS SEWERSHED

BALTIMORE CITY PROJECT 994 REI/DRAYCO

| ate: 06/13/2008 | Basin: JF-19 |
|-----------------|-----------------|
| | ate: 06/13/2008 |

Defect No: 1 Supervisor: E.R. Dye Test Recommended: N

House No: 523 Street Name: E. 22ND Street Type: ST. Source Type: 03 Location: 01 Severity: 02

Sector: 02 Drainage Area: 0

Comments: CLEAN OUT - ABOVE GRADE. BROKEN CAP.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 0994-344_OB01-01.jpg

PAGE 4 OF 4

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY JONES FALLS SEWERSHED

BALTIMORE CITY PROJECT 994 REI/DRAYCO

| Unique Test ID: 344 | Date: 06/13/2008 | Basin: JF-19 |
|---------------------|-------------------------|-------------------------|
| Defect No: 2 | Supervisor: E.R. | Dye Test Recommended: N |
| House No: 1917 | Street Name: GREENMOUNT | Street Type: AVE |
| Source Type: 03 | Location: 08 | Severity: 02 |
| Sector: 02 | Drainage Area: 0 | |

Comments: CLEAN OUT - ABOVE GRADE. BROKEN CAP.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-01 Filename: 0994-344_OB02-01.jpg